

Material Safety Data Sheet For Armco Products

DMS /650,00781

703 Curtis Street Middletown, Ohio 45043

Section I

PRODUCT HAME OR NUMBER	EMERGENCY THAT PHONE NUMBER
6AL-4V AMS-4928	513 / 425 - 5864
MANUFACTURING FACILITY, COMPANY OR SUBSIDIARY	
OREGON METALLURGICAL CORPORATION	
ADDRESS NUMBER, STREET, STATE AND ZIP CODE)	
530 W. 34th Ave., Albany, OR 97321	
DOT HAZARDOUS MATERIAL PROPER SHIPPING NAME (49 CFR 172.101)	DOT HAZARD CLASS (4) CFR 172.101)
N/A	N/A
CHEMICAL FAMILY Titanium Alloy	N/A

ection II CHEMICAL COMPONENT 1 1986 10	C.A.S. NUMBER	١٠,
Titanium	7440-32-6	9 0
11/18		
Aluminum	7429-90-5	6
	· .	
Vanadium	7440-62-2	4
SANTANDO SANTANDA SA	(1	
		······································
3 (\$4.84) (\$2.00 A.C.)	eget afais	
		n andre anne anne entre pelitica des an esta periode de la colonia de la colonia de la colonia de la colonia d

Section III PHYSICAL DATA

Boiling Point	N/A	Solubility in Water	Insoluble	Evaporative Rate (Ethyl ether = 1)	N/A
Vapor Pressure mm Hg @ 20° C	N/A	Specific Gravity (H ₂ O = 1)	4.5	pH =	N/A
Vapor Density (Air = 1)	N/A	Percent Volatile by Volume	0		N/A
APPEARANCE AND ODOR	Odorless	gray ingots and bi	llets		o de la composición del composición de la compos
	Odoriess	gray ingots and bi	Tiera		

Section IV FIRE AND EXPLOSION HAZARD DATA

CLC	OSED CUP FLASH POINT F	N/A LE	L N/A %	UEL N/A %	IGNITION TEMPERATURE	F N/A
i x i	Dry salt or powder					
211	Remove uninvolved	naterial, a	llow fire	to burn ou	t. Cover involved	material with
	salt or powder from	n extinguls	ner. If f	ire in cont	tainer, smother wit	h inert gas.
UNL	Do not use water of	AZARDS other liqu	uld exting	uishers as	hydrogen may be ev	olved.
	Nitrogen and carbon			and other modes, soften and be		

No toxic effects would be expec	ed under normal usage. The "nuisance	100 T
dust" standard would apply.		
		ा इस्टार्क संस्
4		and the second s
The state of the s		
	Maria a sakara awan awan awan awan awan awan awan a	
		<u> </u>
A CONTRACTOR OF THE CONTRACTOR		
	The second secon	
		:
		ktori Milatarian marana maran a majara milataria ya mista
		7.
		entrag Para di managan
ction VI REACTIVITY DATA	The state of the s	
TABLE UNSTABLE	Open flames, excessive heat	
X		
ICOMPATIBILITY (MATERIALS TO AVOID)	Strong oxidizing or reducing agents	
ECOMPOSITION PRODUCTS Titanium dioxi	de, aluminum oxide, vanadium pentoxid	
HAZARDOUS MAY OCCUR CONDITIONS		e
POLYMER- ZATION WILL NOT OCCUR X	17,4	:
ction VII SPILL OR LEAK PROCEDUR		
TERS TO BE FAKEN IN CASE MATERIAL IS RELI Recover material if possible	ASED OR SPILLED	
Landfill in accordance with appl	cable local, state and federal regul	ations
		3420113
	i.	
ction VII PERSONNEL PROTECTION	NFORMATION	
No special precautions		w/s
	# 3 + 4 +	
	<u> </u>	4 g zak k kirokala
	and the second of the second second second	
and the second s	N ANDERSKIED WESTERS	
ction IX SPECIAL PRECAUTIONS AN		
Store as a combustible material -	hard to ignite, but very difficult t	:0
Store as a combustible material -		:0

While the information and recommendations set forth on this data sheet are believed to be accurate as of the present date, ARMCO MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON.

Prepared by: STEPHEN S. FELTON
Corporate Toxic Substances Engineer

en l. Felt

10/15/84